

Notice



CORRECTION
 SERVICE FLASH

PRODUCTION CHANGE
 ADD INFORMATION

FILE NO.

Please add this notice to the Service Manual listed below.

Category: COLOR TELEVISION

Date: NOVEMBER / 01 / 2011

Model: DP42861

Effective from : Chassis No. P42861-11

Destination: U.S.A. / CANADA

REF : No. SM780194-11

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P42841-10. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original Service Manual** and **Notices** for Chassis No. P42841-10 used in Model DP42841 (SM780194).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be changed from **03h** to **04h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000